

Cryogenic Laboratory

Herrick Archives Number 140

A. IDENTIFICATION & LOCATION

1. Name

1.1 Never officially named by Board of Trustees action. However, included in Board of Trustees action of April 11, 1955 naming the "Ohio State University Research Center."

1.2 Alternate names noted:


None

2. Location

2.1 Located at 1286 Kinnear Road. See map below.

2.2 For greater detail, see Sheet 89 in the book of campus maps in the University Archives.

[See Addendum No. 1]



For identification of other buildings shown, see Appendix A.

3. General Description

3.1 Type of construction:

Steel frame with concrete block exterior.

3.2 No. of stories:

One story.

3.3 Increments of construction:

No additions.

3.4 Present area of building as shown in inventory records of Division of Campus Planning:

1,840 square feet gross; 1,555 square feet net assignable

3.5 Volume of building:

24,860 cubic feet.

B. PLANNING & CONSTRUCTION

1. On November 12, 1956 the Board of Trustees approved the plans and related documents prepared by W. E. Linch and authorized the solicitation of bids by contractors. These documents included in addition to Building 140, all of Buildings 128, 129, and 174, and extensive remodeling in Building 073.

2. Bids were received on January 29, 1957 (T).

3. On February 11, 1957 the Board of Trustees awarded contracts to the following contractors:

General: Harry E. Miller & Sons, Inc.

Electrical: Blum Electric Co.

Heating & ventilating: Conditioned Air, Inc.

Plumbing: D. F. Hood

Laboratory Equipment: Johnson Engineering & Equipment Co.

4. The plumbing contract was later readvertised and again was awarded to D. F. Hood on April 8, 1957.

5. Completion and occupancy:

Records in the University Architect's office indicate that the plumbing, heating and ventilating, and electrical contracts were substantially completed on February 28, 1958. The final estimate on the equipment contract is dated May 28, 1958. It should be noted that these dates are for the entire project, and not for Building 140 alone.

C. COST

Not separately reported.

D. PHOTOGRAPHS

1. In Photoarchives:

X 7833

X 7834

John H. Herrick
September 3, 1973

ADDENDUM NO. 1

This building was incorrectly listed in 1962 at 1310 Kinnear Road.

John H. Herrick
August 8, 1977